

Photo documentation – Contract 1B.3/2 Phase II – *The construction of docking-mooring infrastructure on Lower Odra River and on boundary sections of Odra River as well as new aids to navigation*



Photo 1. Works carried out from the water side – Zatoń Dolna location



Photo 2. Protected habitat patch – riparian forest 91E0



Photo 3. Protected site of the marsh spurge *Euphorbia palustris*



Photo 4 Works carried out from the water side at the Zatoń Dolna location



Photo 5 Oil spill containment booms preparation – Szczecin location



Photo 6 Cutting rushes – Osinów Dolny location



Photo 7 Construction facilities on a vessel – Pławidło location



Photo 8 ES Code and OHS list made available to employees



Photo 9 Power generator with additional spill protection on a vessel



Photo 10 Information leaflets on vessels



Photo 11 Installed footbridge platform – Osinów Dolny location



Photo 12 Platform installation – Ługi Górzyckie



Photo 13 Example of water temperature measurement – Pławidło location



Photo 14 Sorbents on a vessel



Photo 15 Constructed dolphins – Kunice location



Photo 16 Beaver (*Castor fiber*) path



Photo 17 Works carried out from the water side – Pławidło



Photo 18 View of the dolphin site – Kunice location



Photo 19 Examples of traces (scent mound) of the beaver *Castor fiber* in the vicinity of the Kunice dolphin site after the completion of the project



Photo 20 Examples of feeding traces (beaver bites) of the beaver *Castor fiber* in the vicinity of the Kunice dolphin site after the completion of the Osinów Dolny investment project